

Safety Task Card



- 11. Do not place hands, tools or any other items near the inlet opening while the equipment is running or connected to power.
- Wait until the hose has cleared before turning equipment off. 12.
- 13. Do not leave equipment unattended when it is operating.
- Always wear a respirator and safety goggles when removing the collection bag. 14.

If you have any concerns, stop and speak with your line manager before proceeding.



List any additional hazards or risks you have identified and control measures required to manage these.	Dust collectors continued	Safety Task Card STCGE 40
	Safe System of Work	
	SOP (Standard Operating Procedures)	