

Savol Beerline Cleaner – BEERLINE CLEANING

HS/TC/037/05 – August 2017



READ BEFORE STARTING



Wear PPE in each step*

APRON, GOGGLES & GLOVES

You MUST refer to the CPAs & Task Cards for your PPE Requirements



1

To remove beer residues, pre-flush system thoroughly as per manufacturer's instructions.




2

Undo cap on bottle and carefully dose into the separate cleaning bottle with the required amount of water for the number of lines being cleaned (see dosage guide below)



3

Pull solution through system several times ensuring a minimum 30 minute contact time.



4

When finished rinse thoroughly with cold water and flush as per manufacturer's instructions.



5

Do not leave solution in system overnight.



6

Re-place cap on bottle and put in safe storage location.



Dosage Guide: Mix 50ml to 10Ltr of cold water. For heavily soiled equipment the concentrate solution may be doubled. (100ml to 10Ltr)

If in doubt about the PPE required, please refer to the separate COSHH Product Assessment or Your HSE Manager.

***PPE as risk assessment recommendation**